


50in Side Discharge Deck





Replaces Toro TimeCutter 5000C Parts

Zero-Turn Mower with 50in Deck - Model 75753

50in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Belts & Pullies

10	R139-2399	139-2399	V-Belt - Traction Drive	1	
11	R119-8820	119-8820	Belt	1	

Spindles

20	R139-3214	117-7267, 121-0751, 139-3214	Spindle Assy	3	
21	R117-7268	117-7268	Shaft- Spindle	3	

Other Parts Available

30	R3219-6	3219-6	Nut - 5/8-18 Gr 8 Hex	3	
31	R453011	01-166-0100, 01-166-0120, 01-166-0270, 01-166-0500, 01-166-0600, 01-166-0620, 132-4593, 2356-3, 237-12, 24-10-AD, 24-11-AD, 24-11-BD, 24-12-AD, 24-12-BD, 30-9310, 32-8190, 3256-24, 3256-3, 3256-36, 3256-4, 453011, 47-9950, 48-9220, 513458, 7-0052	Washer - Flat 3/8 SAE Y/Zinc	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro TimeCutter 5000C Parts

Zero-Turn Mower with 50in Deck - Model 75753

50in Side Discharge Deck



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
32	R323-9	01-150-0190, 01-150-1540, 01-178-0614, 107229, 20-50-AD, 20-50-AGD, 30-9430, 32105-4, 3224-5, 323-9, 513363, 513364, 5377, 908037P	Bolt - Hex HD 3/8-16 x 1-3/4	1	
33	R63-7400	63-7400	Washer - Rebound	3	
34	R104-8301	104-8301, 104-9301, 109-6658, 133-7570	Locknut - 3/8-16 Nylon Flanged	6	
35	R68-2730	1-603299, 68-2730	Wheel - Anti Scalp	3	
36	R112-3977	112-3977	Bolt- Shoulder	3	
37	R110-9981	110-9981	Washer-Plain	1	
38	R115-5059-03	115-5059-03	Mower Blade - High Lift 17.5 in	3	
39	R138-7276	138-7276	Arm - Idler	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.