




Replaces Toro Greensmaster TriFlex 3320 Parts

*DPA Cutting Unit - Models 04613, 04614 & 04615
Left-Hand Carbide Grooming Reel - 04708*



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster TriFlex 3320 Parts



DPA Cutting Unit - Models 04613, 04614 & 04615
Left-Hand Carbide Grooming Reel - 04708

Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Blades

1	R110-2343	110-2343	Groomer Blade - Carbide Tipped - Helix 1.5mm	42	
---	------------------	----------	--	----	--

Other Parts Available

20	R70-1350	70-1350	Spacer - 1/4 Fits Groomer Shaft	82	
21	R120-9653	120-9653	Locknut - 7/8-14 Nylon Jam GR2	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.