



Replaces Toro Greensmaster Flex 21 Parts

Mower - Model 04021

Out-Front Brush Kit - Model 04119



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster Flex 21 Parts

Mower - Model 04021

Out-Front Brush Kit - Model 04119



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Complete Kit

1	R150281		Push Brush Kit - Fits GM800-1000	1	
---	----------------	--	----------------------------------	---	--

Detail Description: Includes 8 ea: R81-0130 Nut; 6 ea: R3296-29 Locknut; 4 ea: R322-42 Bolt, R33103-020 Bolt, R33103-040 Bolt, R400120 Bolt, R453023 Washer, R3253-3 Washer, R443102 Nut, R49-0390 Spacer; 2 ea: R106-8454 Rod Assy, R105-9612 Spring, R32141-36 Adjustment Spring, R150283 Bracket, R443106 Nut; 1 ea: R391235 Brush, R105-9615-01 LH Bracket, R105-9616-01 RH Bracket:

Other Parts Available

10	R105-9602	105-9602	Brush - Incl 2 Ea R150283 Brackets	1	
10	R391235		Brush - 18/22 in Nylon Push	1	
70	R150283	120-9630	Bracket - Brush - Fits R&R Brush Only	2	
70	R106-8450	106-8450	Bracket - Brush	2	
71	R105-9613-01	105-9613-01	Bracket - LH - Brush	1	
72	R105-9614-01	105-9614-01	Bracket - RH - Brush	1	
73	R105-9612	105-9612	Spring - Brush	2	
74	R106-8454	106-8454	Rod Assy - Brush	2	
75	R105-9615-01	105-9615-01	Bracket - LH - Brush	1	
76	R105-9616-01	105-9616-01	Bracket - RH - Brush	1	
78	R32141-36	32141-36	Screw Adjustment	2	
79	R33103-040	33103-040	Bolt - Hex Washer M6-1.0 x 40	4	
80	R49-0390	49-0390	Spacer	4	
81	R33103-020	33103-020	Bolt - Hex Washer M6-1.0 x 20	4	
82	R151379	33114-060, 42-9510	Bolt - Hx HD 8-1.25 x 65mm	4	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster Flex 21 Parts

Mower - Model 04021

Out-Front Brush Kit - Model 04119



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
82	R400120	01-150-0990, 01-178-0416, 02-150-0990, 321-11, 3222-4, 33114-010, 33114-060, 513327, 908470	Bolt - Hex HD 1/4-20 x 2	4	
82	R3234-1	321-11, 3234-1	Bolt - Flanged Serrated Hex HD 3/8-16 x 3/4	4	
83	R33115-030	33115-030, 48-9470	Bolt - Hex HD M10-1.5 x 30	2	
84	R322-42	322-42	Bolt - Hex Tap 5/16-18 x 1-1/2	4	
85	R81-0130	81-0130	Nut - 6mm-1.0 Flanged Lock Nylon	8	
86	R443102	01-188-0420, 22-11-AJD, 3217-5, 33024-00	Nut - 1/4-20 Yellow Zinc	4	
86	R33024-00	33024-00	Locknut - 8mm x 1.25	4	
88	R453023	3256-1, 3256-22, 3256-72, 33094-00	Washer - Flat 1/4	4	
88	R33094-00	33094-00, 93-5914	Washer - Flat - 8mm Hardened	4	
88	R3256-22	24-9-BD, 3-1032, 3256-1, 3256-22, 93-0954, 93-0989	Washer - Flat 1/4 Yellow	4	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster Flex 21 Parts

Mower - Model 04021

Out-Front Brush Kit - Model 04119



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
88	R3253-3	01-166-0070, 01-166-0410, 23-9-GD, 24-7150, 3253-3, 3256-1, 352-167	Washer - Lock 1/4	4	
89	R3296-29	1-804256, 3290-357, 3296-29, 915662P	Locknut - 5/16-18 ESNA	6	
89	R32153-3	119-4038, 22-12-AJFD, 32127-35, 32146-5, 32153-3, 3296-18, 3296-29, 3296-31, N/A	Locknut - 5/16-18 ESNA Zinc	6	
90	RP457-2	01-191-0518, 22-12-AJK, 3218-2, 513299, P457-2	Nut - Jam 5/16-18 Zinc	2	
90	R443106	01-188-0518, 22-12-AJD, 32111-4, 3217-4, 3217-6, 3218-2, 513295, 513412, 915112P, 915978, 915979	Nut - 5/16-18 Y/Zinc Plated	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.