



NGK Spark Plug - ILFR5B11

RN1637



Replaces

Bosch

FR8MII33X

Specifications

Manufacturer

NGK

Box Quantity

4

Package Quantity

1

GERT KAUFMANN Golf Course Management

Graf-Buttler-Strasse 7 Haimhausen, 85778

+498133907773

<https://golfkauf.rrproducts.com/>