



## 3 PVC Union Split Nut Kit RGSNK030



### Details

Split Nut Repair Kit is designed to replace broken union nuts on all True Union 2000 Ball Valves and Sch 80 Union 2000 fittings. Kit includes: 2-Split Nut Halves 1-SS316 Gear Clamp. Full valve pressure rating maintained.

### Specifications

Manufacturer	Spears
Fitting Size	3

**GERT KAUFMANN Golf Course Management**

Graf-Buttler-Strasse 7 Haimhausen, 85778

+498133907773

<https://golfkauf.rrproducts.com/>